Enerplus Resources Visual Internal Inspection Report – Pressure Vessels AI FR 024

Date:	August 13	August 12, 2014				Description			Ves	e e a l		vchar	ngor		Boile	or l	E# 488	859			
		August 12, 2014 John David Kobelsky				Description:				_						DOIL	_	CRN#		P3264.213	
Inspector:						Equipment Name:				Inlet Separator A0490117						_	Serial#	_			
Agent Co:		Integrity Testing Services				Jurisdiction # Manufacturer: F							Vaa								
Owner:		Enerplus Corporation					ctui			fabco Ltd.											
District:		Shallow Gas: Shackleton visual internal inspection was perfor							incer				LSD:					12-26-021-20W3M			
Scope		lacc	essib	le sh	ell an	d head	l surfa	ces, no	ozzles,	weld	ls etc										
Access		/ Manway		ection noz	<u> </u>																
Opening	q ⊢	Sasket surfaces	5	=	Compliant v			Comment			Minor corrosion outside the gasket face.										
	N	Nozzle tube		=		erosion etc.		Comment													
Shell and Head Surfaces	U	Uniform corrosion		√ Ir	nsignificant	amount		Comment													
	d P	Pitting corrosion		□ N	None noted			Comment			Minor pitting found near the 4 o'clock and 7 o'clock region of the West Head. Around 0.100" deep but difficult to measure due to the curvature of the Head.										
		Erosion		✓ N	lone noted			Comment													
	s Ir	Internal Coating		□ F	ull Part	tial 🕢 None		Comment													
	N	Mechanical damage			None noted																
Welds	U	Uniform corrosion			nsignificant	amount	amount		Comment		linor weld attack on the long seam. This was noted on the last inspection.									tion.	
	Р	Pitting corrosion			None noted			Comment													
	V	Welding defects		√ N	None noted			Comment													
		NDE was performed b										Extent									
	Т	Туре		PI	WF	☐ B&V	v [Dr	у		.PI	U	т	RT			Other				
	R	esults:	No NE	DE pe	E performed																
Nozzles	С	Obstructions		None	noted	Comment Some				zzles	zles had mud inside still.										
	s C	Corrosion		None noted		Comme															
	Е	Erosion		None	noted	Comment															
		☐ Vortex brea		r Secui		e Goo		od condition		on	Comment										
		✓ Impingen	nent pl	plate Secu		e Goo		od condition		on	Comment										
		☐ Suction tub		Secu				ood condition		on	Comment										
Attachment		s Demister		▼ Secui		re 🕡 Go		ood condition		on	Comment		Demister is quite dirty				ty				
		Heating coil		Secur		e Go		ood conditio		on	Comment										
		Fire tube		Secur		e Go		ood condition		on	Comment										
				Secure		Good		od co	d condition		Comment										
Inspect	tion	- There was	s mind	ting in the	4 o'clock and 7 o'clock region						the V	West Head.									
Summ		- The long s												out fro	m a	prev	ious	inspect	tion.		
Recomm	enda		The demister was quite dirty a					veu a	at tire	, uiiie	5 01 111	Specii	ЮП.							NCR	
- Monitor the areas of pitting and weld attack at t						the next	inte	rnal i	nspe	ection	1 .										
		mister at the i																			
					Yes No Immediate repair						pairs re	required Future repairs required Replace									
Inventory S			Sto																		
n Off		nspection Interval												Years or Changed to							
	PSV	PSV Interval											Years or Changed to								
									1 /m									Nat'l Bd.: 15019 / API 510/570:			
	Inspe	ector Signatur	tor Signature				12					Jurisdictional Inspector#			#	28139/29975 / IBPV PESL: 274 / Pl Class 1: 169			: 2/4/ PEI		
							,														
	Chief	hief/Senior Signature (if needed)											Jurisdictional Inspector#								