



VALSEAL LTD

8117 DAVIES ROAD
EDMONTON, ALBERTA
T6E 4N1

PHONE: (780) 438-2672 FAX: (780) 434-5166
www.valsealltd.com

INSPECTION REPORT
4513-1

ASVRA MEMBER

Order No.: 35306	Item No.: 27	VSL ID#: 902554
Date: 08/31/10	A#: _____	P.O.No.: CRN 06553050
Customer Name: FORT ENERGY	Address: Corbett 15-10-62-6W5	
Manufacturer: Consolidated	Size: 3-4"	MNPT Orifice: _____
Type: 19096MCI-2-SG-MS-3I-MI-11-1-A	Temp: _____	Capacity: 352.03 LPM
Serial No.: TP67039	Tag #: K690P507GLY	
Set Pressure: 1300 PSI	B.P.: _____	Reset Pressure: PSI
8957 KPA		KPA
PARTICULARS - AS RECEIVED:		Seal: Good Seal Id: VSL
Visible Damage: NONE		
Tag Condition: OK	Body: _____	
Visible Condition: _____	Inlet: OIL	Outlet: OIL
Pretest: SEE COMMENTS	PSI Simmer: _____	Lift: _____
	KPA Simmer: _____	Reset: _____
AFTER CLEANING AND INSPECTION:		
Bonnet Cap: C.C.		
Disc Seat: FLAT	Disc Status: SCORED & PILED	Nozzle Seat: SCORED & PILED
Spring: NO NUMBER	Special Coating: _____	
Condition of Bellows: NONE		
Internal Parts Damage: _____		
Repairs Required: MACHINED AND LAPPED DISC AND NOZZLE SEATS		
Parts Installed: GASKETS		
Parts To Be Ordered: _____		
AFTER ASSEMBLY:		
Test Pressure: PSI	Simmer: 1300	Set: 1300
		Reset: 1260
Back Pressure Test: ACCEPTED	Leakage as per manufacturer's spec or API 527	bpm 0 cc/hr
COMMENTS: K690 GLYCOL PUMP (P507)	VALVE STARTED TO LEAK FROM 400 PSI WHEN PRE-TESTING	

Certified: _____
TP 1/

Date: 9/2/10